

## Sensor-Guide

Sensor Head	Model	Signal Output	Mesurement Range	Favourite Application	Data Sheet
Sensor Head	MOHS 2.1	a) 1x programmable threshold (open collector)	0,5 ... 4,0 Vol.-%	room monitoring	<a href="#">download</a>
	MOHS 2.2	a) 1x programmable threshold (open collector)		industrial monitoring systems	<a href="#">download</a>
	MOHS 3	a) analogue 3 ... 5 V (non-linear) b) 1x programmable threshold (open collector)	1 ... 100 Vol.-%	industrial applications process monitoring process controlling	<a href="#">download</a>
	MOHS 3.Z	a) optional (linear): • 0/4 ... 20 mA • 0/2 ... 10 mA • 0/1 ... 5 mA b) 1x programmable threshold (open collector) c) LC-Display			<a href="#">download</a>
	MOHS 4	a) RS 232 b) 0/4 ... 20 mA c) 2x programmable threshold (open collector) d) 1x programmable common alarm e) LC-Display			<a href="#">download</a>